

PRESSURE/TORQUE CONVERSION CHART

PRESSURE IN PSI	FT. LBS.	N-m	3MD
1000	270	366	
1200	330	447	
1400	390	529	
1600	465	630	
1800	520	705	
2000	600	813	
2200	675	915	
2400	740	1003	
2600	800	1085	
2800	865	1173	
3000	930	1261	
3200	990	1342	
3400	1050	1424	
3600	1120	1518	
3800	1180	1600	
4000	1240	1681	
4200	1300	1763	
4400	1360	1844	
4600	1425	1932	
4800	1490	2020	
5000	1560	2115	
5200	1585	2149	
5400	1680	2278	
5800	1740	2359	
6000	1800	2440	
6200	1850	2508	
6400	1900	2576	
6600	1960	2657	
6800	2020	2739	
7000	2080	2820	
7200	2150	2915	
7400	2210	2996	
7600	2270	3078	
7800	2330	3159	
8000	2395	3247	
8200	2460	3335	
8400	2535	3437	
8600	2585	3505	
8800	2645	3586	
9000	2725	3695	
9200	2780	3769	
9400	2850	3864	
9600	2910	3945	
9800	2975	4034	
10000	3030	4108	

