

IBT/MXTA-10 Torque Chart 1-1/2" Dr.



Pump Pressure in PSI	Ft. Lbs. Torque	NM of Torque	Pump Pressure in BAR
1500	1625	2203	103
1600	1733	2350	110
1800	1948	2641	124
2000	2164	2934	138
2200	2384	3232	152
2400	2605	3532	166
2600	2825	3830	179
2800	3046	4130	193
3000	3266	4428	207
3200	3488	4729	221
3400	3711	5031	234
3600	3933	5332	248
3800	4156	5635	262
4000	4378	5936	276
4200	4596	6231	290
4400	4815	6528	303
4600	5033	6824	317
4800	5251	7119	331
5000	5469	7415	345
5200	5692	7717	359
5400	5913	8017	372
5600	6136	8319	386
5800	6358	8620	400
6000	6562	8897	414
6200	6803	9224	428
6400	7025	9525	441
6600	7247	9826	455
6800	7470	10128	469
7000	7693	10430	483
7200	7917	10734	497
7400	8141	11038	510
7600	8365	11341	524
7800	8589	11645	538
8000	8813	11949	552
8200	9036	12251	566
8400	9260	12555	579
8600	9484	12859	593
8800	9708	13162	607
9000	9931	13465	621
9200	10151	13763	634
9400	10371	14061	648
9600	10590	14358	662
9800	10810	14656	676
10000	11029	14953	690

Tool Owner:

Serial Number:

Calibrated By:
Torqbuddy

Due Date:

Accuracy of Tool to Chart Within 3%:

Please call us at:
+27 32 9470577

Manufacturer: Wren
Model Number: 10IBT
Max Pressure 10,000 PSI